



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 10

1200 Sixth Avenue
Seattle, Washington 98101

SPCC

CERTIFIED MAIL

MAR 03 1994

Reply to
Attn of: HW-114

MAR 1994

Bob Laycock, Maintenance Supervisor
Pacific Western Forest Industries
58144 Old Portland Road
PO Box 599
St. Helens, OR 97051

Dear Mr. Laycock:

On November 10, 1993 an inspection was conducted by a representative of the Environmental Protection Agency (EPA) at your St. Helens, Oregon oil storage facility. At that time you were found to be in violation of the federal oil spill regulations (40 CFR 112) as no Spill Prevention, Control and Countermeasure (SPCC) plan was available for our on-site review.

Some time has passed since the EPA inspection when you were advised of the need for a SPCC plan. If you prepared an SPCC plan during that time, you are requested to send a copy of your SPCC plan to my attention within 48 hours of receipt of this letter. If no SPCC plan has been prepared for your oil storage facility, then a SPCC plan will be required to be prepared within 60 days of receipt of this letter. This SPCC plan will require EPA's approval and must be sent to my attention on or before the 60 days allowed. Failure to have a written spill prevention plan may result in substantial civil penalty being imposed.

In order to help you with your spill prevention work I am enclosing a brochure on preparing SPCC plans. If you have any questions concerning this matter you can reach me or Carl Kitz, of my staff, at the above address or by calling 553-1263.

Sincerely,

Carl Kitz

for Bub Loiselle, Chief
Site Response Section

cc: Office of Regional Counsel
000



U.S. ENVIRONMENTAL PROTECTION AGENCY
Oregon Operations Operations Office
Site Visit Checklist for UST

A. DATE: 2.24-94 TIME: 400p FACILITY ID#: 5471

BACKGROUND

Pacific Western
Facility Name Forest Industries Contact Charles L. Mintken
Address 58144 Old Portland Rd Title Pres / Gen. Mgr *
City St. Helens State OR Zip 97051 Phone (503) 397-4300
Other (type operation, Directions to locate) shut down mill Owner Bankruptcy - Bank
OLD CZ Mill; alias * Trustee?
Multnomah Pkgood
David Lawrence, Local Distrib
pumped out?
LOI SITE ☐ NOT LOI ☒
RETAIL SALES ☐ NOT RETL ☒
GOVERNMENT ☐ PRIVATE ☒

UST DATA

B. TANKS SIZE PRODUCT DATE INSTALLED TYPE MATERIAL

Found 1. North ? 3 1/4" product
2. South 3 1/2" ci
3. _____
4. _____
5. _____
6. Present owner - 2 years
Notes T's not used 2 1/2 ++ years

C. TANK LEAK DETECTION METHOD (DIC + TTT¹) (ATG) (MW) NOTES ON REVERSE ☒

VIO 1. _____ NOTES _____
2. _____
3. _____

D. PIPING (AFR/S, CONT. ALARM) + (MW, TTT¹, INTERSTITIAL MON)
PRESSURE _____ SUCTION _____ NOTES OVER _____

VIO 1. _____ NOTES _____
2. _____
3. _____

¹ LOI DEFERRAL - TEMPORARY

INSPECTOR _____ (SIG)

E. INSURANCE OR WHAT MECHANISM

_____ RISK RETENTION GROUP

_____ SELF INSURED

_____ INSURED BY _____

_____ LOI DEFERRAL IN EFFECT

_____ NONE OF ABOVE

MISC. NOTES: _____

INSURANCE PLANS: _____

UPGRADE PLANS: _____

SUMMARY (BELOW) _____

MW: Monitoring Well, DIC: is Daily Inventory, TTT: Tank Test

AFR: Auto Flow Restrictor, MTG: is Manual gauging

ATG: Auto Tk Gauging LOI: Letter of Intent to Upgrade

(_____) _____

(_____) _____

(_____) _____

(_____) _____

SUMMARY: (Findings, Conclusions, Follow-up, Tech. Asst. Given) _____

Do letter refer to JED

DATE

1/24/14

INSPECTOR

Ran Celis

1/5/14 RIC